


Expert Technical Inspection

Covers over 200+ checkpoints including engine, transmission, suspension, brakes, electrical systems, and safety features, and others

Digital Report & Transparency

100% independent and unbiased, complete visibility before delivery.

Trusted by Customers

Thousands of happy customers have chosen PDIwala for their new vehicles


PDIwala – Your Trusted Partner in Pre-Delivery Assurance
VEHICLE INSPECTION REPORT

Inspection Details

Client Name	Saras Webtech	Inspection Date and Time	01-Dec-2025
Inspection By	manju Chauhan	Submission Date and Time	29-Sep-2025
Report Generated On	29-Sep-2025	Car Details	Maruti-maintest - Xyz

Vehicle Details

Dealer / Car Owner	Manju
Car Registration No.	MH123
Car Make	Maruti-maintest
Car Model	Xyz
Car Chasis / SR No.	MJ1234
Odometer reading	97986865 Kms

Initial Vehicle Images



Inspections Report Details

Question 0 - FRONT BUMPER	
Status	Remark
OK	
Question 1 - RIGHT FENDER	
Status	Remark
OK	
Question 2 - REAR RIGHT DOOR	
Status	Remark

Question 2 - REAR RIGHT DOOR

OK	

Question 3 - RIGHT DOOR

Status	Remark
OK	

Question 4 - REAR RIGHT SIDE QUATER PANEL

Status	Remark
OK	

Question 5 - REAR BUMPER

Status	Remark
OK	

Question 6 - DICKY

Status	Remark
OK	Rear skcertch

Question 7 - REAR TAIL LIGHT

Status	Remark
Not OK	Slite

Question 8 - REAR UNDER BODY

Status	Remark
OK	

Question 9 - REAR LEFT QUATER PANEL

Status	Remark
OK	

Question 10 - REAR LEFT DOOR

Status	Remark
OK	

Question 11 - FRONT LEFT DOOR

Status	Remark
OK	

Question 12 - LEFT FENDER

Status	Remark
OK	

Question 13 - LEFT RUNNING BOARD

Status	Remark
OK	

Question 14 - ALL SIDE VIEW

Status	Remark
OK	

Question 15 - TYRES CONDITION

Status	Remark
OK	



Question 16 - FRONT / REAR WINDSHEILD

Status	Remark
--------	--------

Question 16 - FRONT / REAR WINDSHEILD

Question 17 - TOP VIEW

Status	Remark
OK	

Report Acknowledgment

We hereby acknowledge the completion of the pre-delivery inspection of the vehicle mentioned above. The findings, remarks, and images in this report have been discussed and confirmed by both parties.

Customer Signature

Name: Saras Webtech
Date: 01-Dec-2025

PDI Inspector Signature

Name: manju Chauhan
Date: 01-Dec-2025

This is a system-generated report. No signature is required.

Terms And Conditions

- The Inspection Report is an assumption as some parts in a vehicle cannot be inspected (Internal parts in the vehicle need to be opened for further inspection).
- The report is valid for only 24 hrs. after inspection of the Vehicle (Damages may occur by External means)
- We do not thoroughly check any parts of the car, as it is a used car, we do not guarantee the parts
- Some parts may deteriorate quickly due to geographical conditions, weather and usage.
- We are not responsible for some cars that may have overheating/electronic parts problems
- We do not take responsibility for any used parts/accessories
- We are not responsible if the vehicle part during analysis and vehicle parts and inspection parts are changed during delivery
- The report we provide will depend on the current condition of the vehicle
- We Ensure that this report is 99.9% Accurate.
- We are not conducting any test drives for PDI Car.